

Entrance to Fellowship Hall



Roof trusses are being installed for the roof of the covered entrance to Fellowship Hall (left).

The ceiling has been framed in under the drive-through roof, and electric conduit is being installed for lights.



Workers begin to apply stucco to the roof pillars (above).

Stucco has been nearly completed on the front of the entrance way, providing a glimpse of how the finished building will look (below).

